




1. Turret board to Pots:



2. Turret board to Pots:




5. Connect the red wire from Output transformer to PointB of 32+32uF/500V Cap;
Connect the other red wire from Choke to PointB of 32+32uF/500V Cap;
Connect the red wire from Pin "On" of Standby SW to PointB of 32+32uF/500V Cap;



END OF WIRING!

- *Load a 500mA fuse into the HT Fuse Holder;
- *Tighten the Ground Screw using a DIA=5.0 nut;



Completion of assembly

- put Marshall-style knobs on all pots and the output selector;
- add some glue to holds the indicator tight;
- clean the inside just in case there are solder ball leftover that leads to possible short circuit;
- put tubes on;
- load a correct rating fuse into the fuse holder;
- You are ready to do some bench testing;

